

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/12/2024

Submitted Date:

11/14/2024

Document Number:

707801216

## FIELD INSPECTION FORM

 Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
 335003 \_\_\_\_\_ Ramsey, Scott \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_
**Operator Information:**
 ECMC Operator Number: \_\_\_\_\_ 10456 \_\_\_\_\_  
 Name of Operator: CAERUS PICEANCE LLC \_\_\_\_\_  
 Address: 1001 17TH STREET #1600 \_\_\_\_\_  
 City: \_\_\_\_\_ DENVER \_\_\_\_\_ State: \_\_\_\_\_ CO \_\_\_\_\_ Zip: \_\_\_\_\_ 80202 \_\_\_\_\_
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 11 \_\_\_\_\_ Number of Comments
- 1 \_\_\_\_\_ Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269190	WELL	PR	09/06/2007	GW	045-09331	BENZEL 36-8C5 (H36X)	PR
269285	WELL	PR	01/07/2008	GW	045-09340	BENZEL 36-8B5 (H36X)	PR

**General Comment:****ECMC Inspection Report Summary**

On Tuesday 11/12/2024, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus H36X, at Location # 335003 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Some areas of access show signs of lack of stabilization/ compaction.
2. Lack of battery signage

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Provide proper signage	Date:	01/03/2025
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911/970-285-2615		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	500 gallon methanol tank in metal containment		
Corrective Action:			Date:
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 269190 Type: WELL API Number: 045-09331 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 269285 Type: WELL API Number: 045-09340 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Ditches				
		Compaction				Light compaction in areas
Gravel						Sparse to none
Compaction						Light compaction in areas

Comment: Places with sparse to no gravel & light compaction are present on lease road and location. Sparse to no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403995470	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6787183">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6787183</a>
707801223	Photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6787154">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6787154</a>