

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/12/2024

Submitted Date:

11/14/2024

Document Number:

708700063

FIELD INSPECTION FORM

Loc ID 333566 Inspector Name: Kosola, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
, O'hare		mollieo@maralexinc.com	San Juan inspections
Bechtolt, Phoebe		pbechtolt@maralexinc.com	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214932	WELL	PA	01/03/2022	GW	067-06537	SHELHAMMER 1	EI
465913	SPILL OR RELEASE	AC	07/29/2019		-	Shelhammer Compressor	EI

General Comment:

This is an environmental inspection to document status of Remediation 21214. Partially buried vessel excavation appears to have impacts from a release from the tank. See corrective action.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

TRASH

Comment: [Trash in soil pile and other trash on location. See attached photos](#)

Corrective Action: [Comply with Rule 606](#)

Date: 11/21/2024

Overall Good:

Spills:

Type

Area

Volume

Comment: [Evidence of possible release from partially buried vessel. See attached photos.](#)

Corrective Action: [Conduct spill investigation and conduct soil sampling around tank as part of Remediation 21214. Submit soil sample results on Form 27 Supplemental.](#)

Date: 12/31/2024

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 214932 Type: WELL API Number: 067-06537 Status: PA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 465913 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403994814	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6786583
708700064	Environmental inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6786581