

## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 25-20 Pad

Location # 335236



Photo # 950 From entrance to location



Photo # 951 Location



## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 25-20 Pad

Location # 335236



Photo # 952 Location



Photo # 953 Location



## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 25-20 Pad

Location # 335236



Nov 21, 2024 at 3:34:19 PM  
CO

Photo # 954 Location



Nov 21, 2024 at 3:34:57 PM  
CO

Photo # 955 Location



## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 25-20 Pad

Location # 335236



Photo # 956 Location




Photo # 957 Location



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 25-20 Pad

Location # 335236



**Photo # 958 Mechanical Condition – possible dump line leak**



**Photo # 959 Mechanical Condition – possible dump line leak**





## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 25-20 Pad

Location # 335236



**Photo # 960 Mechanical Condition – possible dump line leak**



**Photo # 961 Mechanical Condition – possible dump line leak**





## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 25-20 Pad

Location # 335236



**Photo # 962 Mechanical Condition – possible dump line leak**



**Photo # 963 Mechanical Condition – possible dump line leak**



## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 25-20 Pad

Location # 335236



**Photo # 964 Mechanical Condition – possible dump line leak**



**Photo # 965 Mechanical Condition – possible dump line leak**