

WELL NAME: NEW ELK 36-01, API #: 071-09238, INSP. # 716300290



PHOTO 1: WELL SIGN



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



PHOTO 2: LOCATION.





PHOTO 3: WELLHEAD AND EQUIPMENT.



PHOTO 4: AREA OF IMPACTED SOIL AROUND WELLHEAD APPEARS TO BE FROM LEAKING DRIVEHEAD. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 12/1/2024.



PHOTO 5: OILY WASTE FROM LEAK IN HYDRAULIC MOTOR HAS FILLED SKID AND HAS SPILLED OVER CAUSING IMPACT SOIL SURROUNDING SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE OR TREAT IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 11/22/2024 TO DRAIN SKID 12/21/2024 DO REPAIR EQUIPMENT AND STOP LEAKS.