

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/21/2024

Submitted Date:

11/23/2024

Document Number:

713400486**FIELD INSPECTION FORM**Loc ID 312667 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1700 LINCOLN ST STE 3950City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, LARAMIE		cogccnotifications@laramie-energy.com	
Toews, Wesley		wtoews@blm.gov	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259337	WELL	PR	05/27/2005	GW	077-08724	WAGON TRACK FEDERAL 12-6	PR

General Comment:**CECMC Inspection Report Summary**

On 11/21/2024 at approximately 11:19 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection at LARAMIE ENERGY LLC Wagon Track Federal/12-6 Pad at Location ID #312667 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1. Equipment - Tank port open to wildlife/wildlife hazard/ available for entry by wildlife with a CA date of 11/30/2024
2. Tanks and Berms - Multiple holes and tears in secondary containment liner/liner needs maintenance also the liner is deteriorating and lacks integrity with a CA date 12/14/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign is weathered & cracked but still legible		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-800-891-6191/911

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Light debris, refer to photos		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe rail fencing		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Plunger Lift	# 1			
Comment:	Well on plunger lift			
Corrective Action:				Date:
Type: Ancillary equipment	# 2			
Comment:	Flameless gas infrared catalytic heater			
Corrective Action:				Date:
Type: Deadman # & Marked	# 2			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:	Summit midstream			
Corrective Action:				Date:
Type: Horizontal Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Other	# 1			
Comment:	Tank port open to wildlife/wildlife hazard/ available for entry by wildlife			
Corrective Action:	Comply with CECMC wildlife rules			Date: 11/30/2024
Type: Bradenhead	# 1			
Comment:	No form of pressure monitoring equipment. Bradenhead valve is accessible			
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:	No telemetry on tank				
Corrective Action:					Date:

Paint

Condition	Inadequate
Other (Content)	
Other (Capacity)	95 bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Multiple holes and tears in secondary containment liner/liner needs maintenance, also the liner is deteriorating and lacks integrity			
Corrective Action:	The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs			Date: 12/14/2024

Venting:

Yes/No	NO
--------	----

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	259337	Type:	WELL	API Number:	077-08724	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Berms				
Ditches						
		Ditches				
Berms						
Waddles						
		Culverts				
Sediment Traps						
		Sediment Traps				
		Compaction				
Gravel						Sparse to none in some areas
		Check Dams				
Compaction						
Rip Rap						

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Equipment & Tanks and Berms for corrective actions and Housekeeping for comments.	popejoyd	11/23/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400487	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6798559