

# Inspection Photos

Loc: 333349

Operator: **OXY USA INC**

Inspection Date: 11/25/2024

County: Huerfano



Inspection Photos



**Photo 1.** Facing northwest toward the location.



## Inspection Photos



**Photo 2.** There is a material pile stored from the excavated pit. The berm around the pile is inadequate and material has fallen outside of the containment.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:333349 | Date: 11/25/2024

Inspection Photos



**Photo 3.** Facing toward the nit which has been excavated for remediation.



Inspection Photos



**Photo 4.** Facing northwest toward the wellsite.



Inspection Photos



Photo 5. The orange fence is displaced around the excavated area near the well. .

