

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/27/2024

Submitted Date:

11/27/2024

Document Number:

694500737

FIELD INSPECTION FORM

Loc ID 324697 Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
,		cogcc@kpk.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212467	WELL	PR	11/01/2019	OW	057-06361	MCCALLUM UNIT 121	EI

General Comment:

On 11/21/24, ECMC staff Kris Neidel inspected the Mccallum #121 well pad. Weather was 35 degrees, mostly clear, snow cover was present on the pad and in the area. The following was observed; water, ice and snow around the wellhead, potential salt staining on wellhead and adjacent fencing (see photo #2), . The well was pumping at the time of inspection. Corrective Action: Operator shall comply with Rules 608.e, 902.c, and 912 including 912.a.(1, 2, and 5), and 912.b. install belt guard.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Prime Mover	#		corrective date
Comment: no belt guard.			
Corrective Action: install belt guard.			Date: 01/06/2025

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 212467 Type: WELL API Number: 057-06361 Status: PR Insp. Status: EI

Producing Well

Comment: [pumping](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500740	photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6804191