

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/25/2024

Submitted Date:

11/27/2024

Document Number:

715201225

**FIELD INSPECTION FORM**

Loc ID: 483130 Inspector Name: Welsh, Brian On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10360  
Name of Operator: NAVEX RESOURCES LLC  
Address: 1020 E LEVEE STREET, SUITE 130  
City: DALLAS State: TX Zip: 75207

**Findings:**

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Beiker, Mark		mabieker@gmail.com	
Walters, Leann	(214) 346-2212	lwalters@trekresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
483495	WELL	TA	05/01/2024	OW	063-06353	Pfaffly 1-12	TA

**General Comment:**

SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location  
Form 5B (403992770) has been approved. Sundry Notice has been filed for TA status.  
Passing MIT was performed on 4/19/24 Form 21 (403818796)

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:			Date:
Type	OTHER		
Comment:	Lease sign by county road at location entrance		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	FWKO has been removed from location. Waddles and pvc pipe is still on location. Install waddles and remove piping from location		
Corrective Action:	Comply with rule 606		Date: 12/25/2024
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Other	# 0		corrective date
Comment:	Hydraulic lift trailer has been removed from location		
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 483495 Type: WELL API Number: 063-06353 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Waddles have been stored on location since last inspection on 3/7/24

Corrective Action: Waddles need to be installed to prevent further erosion leading off of location

Date: 12/25/2024

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715201233	location photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6804573">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6804573</a>