

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/25/2024

Submitted Date:

12/01/2024

Document Number:

713400502

FIELD INSPECTION FORM

| | | | | |
|---|-----------------------------------|---|-------------------|---|
| Loc ID 334544 | Inspector Name: Popejoy, Dusty | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 24 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE |
| Operator Information: ECMC Operator Number: 10433 Name of Operator: LARAMIE ENERGY LLC Address: 1700 LINCOLN ST STE 3950 City: DENVER State: CO Zip: 80203 | | | | |
| | | | | |
| | | | | |

| | | | |
|-----------------------------|-------|---------------------------------------|---------|
| Contact Information: | | | |
| Contact Name | Phone | Email | Comment |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| , LARAMIE | | cogccnotifications@laramie-energy.com | |

| Inspected Facilities: | | | | | | | |
|-----------------------|------|--------|-------------|------------|-----------|----------------|-------------|
| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
| 281631 | WELL | PR | 06/24/2008 | GW | 077-08968 | BLACKMAN 14-14 | PR |
| 281632 | WELL | PR | 03/06/2009 | GW | 077-08969 | BLACKMAN 14-13 | PR |
| 281634 | WELL | PR | 08/20/2006 | GW | 077-08970 | BLACKMAN 14-12 | PR |
| 281635 | WELL | PR | 01/01/2011 | GW | 077-08971 | BLACKMAN 14-6 | PR |
| 281636 | WELL | PR | 09/08/2006 | GW | 077-08972 | BLACKMAN 14-5 | PR |
| 282491 | WELL | PR | 12/01/2017 | GW | 077-08987 | BLACKMAN 22-1 | PR |
| 282492 | WELL | PR | 04/23/2009 | GW | 077-08986 | BLACKMAN 23-3 | PR |
| 282493 | WELL | PR | 04/23/2009 | GW | 077-08985 | BLACKMAN 23-4 | PR |
| 282852 | WELL | PR | 12/01/2017 | GW | 077-09005 | BLACKMAN 15-8 | PR |
| 282853 | WELL | PR | 06/24/2008 | GW | 077-09004 | BLACKMAN 15-9 | PR |

| |
|--|
| General Comment: CECMC Inspection Report Summary On 11/25/2024 at approximately 15:02 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection at LARAMIE ENERGY LLC Blackman/14-12 Pad at Location ID #334544 in Mesa County, Colorado. This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area. During the inspection, the following compliance issues were observed: 1. Housekeeping - Weeds/undesirable plant species on location with a CA date of 12/8/2024 2. Tanks and Berms - Multiple holes in secondary containment liner/liner needs maintenance with a CA date of 12/21/2024 A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. |
|--|

Location**Lease Road:**

| | | | |
|-------------------|--------|-------|--|
| Type | Access | | |
| comment: | Access | | |
| Corrective Action | L | Date: | |

Overall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|--|-------|--|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Sign at entrance to location | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Chemical labeling on tanks on separators | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--------------------|-------|--|
| Comment: | 1-800-891-6191/911 | | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | WEEDS | | |
| Comment: | Weeds/undesirable plant species on location, refer to photos | | |
| Corrective Action: | Oil & gas locations will be kept free of undesirable plant species | Date: | 12/08/2024 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-------------------------------------|-------|--|
| Type | LOCATION | | |
| Comment: | Barbed wire fencing around location | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|---|--|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 10 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 10 | | |
| Comment: | All wells on plunger lift | | |
| Corrective Action: | | | Date: |
| Type: Vertical Heated Separator | # 8 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 10 | | |
| Comment: | Wells 14-14 & 14-16 bradenheads have no form of pressure monitoring equipment. All other Bradenhead valves are accessible with telemetry for monitoring. | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| METHANOL | 1 | OTHER | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 500 gal | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|---------------------------------|---------------------|---------------------|-------------|--------|
| | | | | | |
| Comment: | Centralized containment | | | | |
| Corrective Action: | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CONDENSATE | 6 | 300 BBLS | STEEL AST | | , |
| Comment: | 2 tanks equipped with telemetry | | | | |
| Corrective Action: | | | | | |
| Date: | | | | | |

Paint

| | | | | | |
|--------------------|---|---------------------|---------------------|-------------|------------------|
| Condition | Inadequate | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Inadequate | Walls Insufficient | Base Insufficient | Inadequate | |
| Comment: | Multiple holes in secondary containment liner/liner needs maintenance | | | | |
| | Centralized containment | | | | |
| Corrective Action: | The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs | | | | Date: 12/21/2024 |
| Venting: | | | | | |
| Yes/No | NO | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Flaring: | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

| Inspected Facilities | | | | | | | | | |
|--|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 281631 | Type: | WELL | API Number: | 077-08968 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 281632 | Type: | WELL | API Number: | 077-08969 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 281634 | Type: | WELL | API Number: | 077-08970 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 281635 | Type: | WELL | API Number: | 077-08971 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 281636 | Type: | WELL | API Number: | 077-08972 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 282491 | Type: | WELL | API Number: | 077-08987 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 282492 | Type: | WELL | API Number: | 077-08986 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 282493 | Type: | WELL | API Number: | 077-08985 | Status: | PR | Insp. Status: | PR |

| | | | | | | | | | |
|--|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | Date: | | | | | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 282852 | Type: | WELL | API Number: | 077-09005 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | Date: | | | | | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 282853 | Type: | WELL | API Number: | 077-09004 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | Date: | | | | | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | | | | | | |
| | | Compaction | | | | |
| Compaction | | | | | | |
| Ditches | | | | | | |
| | | Ditches | | | | |

Comment: Limited storm water inspection due to snow cover

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|--|----------|------------|
| Please refer to Housekeeping & Tanks and Berms for corrective actions. | popejoyd | 12/01/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 713400503 | Inspection Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6806774 |