

## Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612



Dec 6, 2024 at 1:15:41 PM  
CO

Photo # 2694 From entrance to location



Dec 6, 2024 at 1:15:44 PM  
CO

Photo # 2695 From entrance to location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612




Photo # 2696 Location



Photo # 2697 Location



## Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612



Photo # 2698 Location



Photo # 2699 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612



Photo # 2700 Location



Photo # 2701 Location





## Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612



Photo # 2702 Location



Photo # 2703 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612




Photo # 2704 Location



Photo # 2705 Location



## Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612



Photo # 2706 Open ended load line



Photo # 2707 Same open ended load line



## Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612



Photo # 2708 Unused hose in secondary containment



Photo # 2709 Debris



## Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612



**Photo # 2710 Methanol tank labeling damaged/tank is missing required information**



**Photo # 2711 Methanol tank labeling damaged/tank is missing required information**

## Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2 Pad

Location # 311612



**Photo # 2712 Tank label weathered & starting to become illegible**

