

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/10/2024

Submitted Date:

12/14/2024

Document Number:

708905246**FIELD INSPECTION FORM**Loc ID 323952 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: 401216537**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**32 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Toews, Wesley		wtoews@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211343	WELL	PR	10/12/1997	GW	045-07103	FEDERAL RU 14-6	PR

**General Comment:****CECMC Inspection Report Summary**

On 12/10/2024 at approximately 15:50 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC FEDERAL RU 14-6 Frac Pad.

Location # 323952 in Garfield County Colorado.

Location is within High Priority/NSO/Black Bear Habitat areas &amp; in close proximity to Density Habitat area.

Location is within Rule 411a Surface Water External Buffer.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Open ended load line with a CA date of 12/21/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	1 chemical tank - pipe rail fence		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:		Date:	

Type	WELLHEAD			
Comment:	Pipe rail fence			
Corrective Action:			Date:	
<b>Equipment:</b>				corrective date
Type: Bradenhead	# 1			
Comment:	Pressure transducer & Taylor plug located on bradenhead, bradenhead valve is accessible.			
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Open ended load line			
Corrective Action:	All load lines will be capped or plugged		Date:	12/21/2024
Type: Ancillary equipment	# 1			
Comment:	Catalytic heater			
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Thermogen			
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:	Summit Midstream Please refer to FORM 2A document #'s 400661709 & 401216537 Equipment not listed in FORM 2A			
Corrective Action:			Date:	
Type: Plunger Lift	# 1			
Comment:	Well on plunger lift			
Corrective Action:			Date:	
Type: Bird Protectors	# 6			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Pump house Please refer to FORM 2A document #'s 400661709 & 401216537 Pumps contained in pump house are not listed in operators FORM 2A/not in compliance with CECMC rules			
Corrective Action:			Date:	
Type: Emission Control Device	# 2			

Comment:	Please refer to FORM 2A document #'s 400661709 & 401216537			
	ECD's are not listed in operators FORM 2A/not in compliance with CECMC rules			
Corrective Action:			Date:	
Type: Ancillary equipment	# 3			
Comment:	Chemical tanks			
	Please refer to FORM 2A document #'s 400661709 & 401216537			
	Equipment not listed in FORM 2A or FORM 4 SUNDRY			
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLS	STEEL AST		,	
Comment:	Tank equipped with telemetry					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate					
Comment:	Centralized containment					
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST		,	
Comment:	Tanks equipped with telemetry					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
Comment:	Centralized containment				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	HEATED STEEL AST		,	
Comment: Tanks equipped with telemetry						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment: Centralized containment				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	5	300 BBLs	STEEL AST		,	
Comment: 3 of 5 tanks are equipped with telemetry						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment: Centralized containment				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	211343	Type:	WELL	API Number:	045-07103	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				Light compaction in some sections
Compaction						Light compaction in some areas
Gravel						Sparse to none in some visible areas
		Ditches				
Ditches						
				Material Handling And Spill Prevention		Chemical tank containments
		Gravel				Sparse to none in sections
		Culverts				
Retention Ponds						

Comment: [Some fluid in 1 chemical tank containment, may need maintenance in the near future.](#)

[Limited Stormwater inspection due to snow](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Equipment for corrective action</a>	smelserw	12/14/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708905247	Inspection 708905246 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6825660">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6825660</a>
708905248	Inspection 708905246 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6825661">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6825661</a>