

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/17/2024

Submitted Date:

12/17/2024

Document Number:

708303214**FIELD INSPECTION FORM**
 Loc ID 335546 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Smelser, Wayne		wayne.smelser@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292287	WELL	PR	09/17/2007	GW	045-14673	ROBINSON C 13	PR
292288	WELL	PR	09/07/2011	GW	045-14672	Robinson C4	PR
292289	WELL	PR	09/01/2024	GW	045-14671	ROBINSON C7	PR
292290	WELL	PR	09/18/2007	GW	045-14670	ROBINSON C14	PR
292291	WELL	PR	01/17/2012	GW	045-14669	Robinson C11	PR
292292	WELL	PR	01/17/2012	GW	045-14668	Robinson C9	PR
292293	WELL	PR	01/17/2012	GW	045-14667	Robinson C1	PR
298259	WELL	PR	06/22/2012	GW	045-17104	ROBINSON C12	PR
298260	WELL	PR	01/15/2013	GW	045-17105	ROBINSON C3	PR
298261	WELL	PR	09/01/2021	GW	045-17106	ROBINSON C6	PR
298262	WELL	PR	09/05/2011	GW	045-17107	ROBINSON C8	PR
298263	WELL	PR	06/26/2012	GW	045-17108	ROBINSON C2	PR
298264	WELL	PR	06/26/2012	GW	045-17109	ROBINSON C10	PR

**General Comment:**

CECMC Inspection Report Summary

On 12/17/2024 at approximately 12:25, Compliance Inspector Matthew Morris conducted a follow-up inspection at TEP ROCKY MOUNTAIN LLC, ROBINSON/C PAD at Location ID #335546 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

- 1) Wildlife entry hazard at separators
- 2) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911/(970)285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Gas Meter Run	# 14		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 11		
Comment:			
Corrective Action:		Date:	

Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 13		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 14		
Comment:	Wildlife entry hazard on separator.		
Corrective Action:	Secure equipment to prevent wildlife entry.		Date: 01/02/2025
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:			Date:
Type: Bradenhead	# 13		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities						
Facility ID:	292287	Type:	WELL	API Number: 045-14673	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	292288	Type:	WELL	API Number: 045-14672	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	292289	Type:	WELL	API Number: 045-14671	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	292290	Type:	WELL	API Number: 045-14670	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	292291	Type:	WELL	API Number: 045-14669	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	292292	Type:	WELL	API Number: 045-14668	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	292293	Type:	WELL	API Number: 045-14667	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	298259	Type:	WELL	API Number: 045-17104	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	298260	Type:	WELL
API Number:	045-17105	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	298261	Type:	WELL
API Number:	045-17106	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	298262	Type:	WELL
API Number:	045-17107	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	298263	Type:	WELL
API Number:	045-17108	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	298264	Type:	WELL
API Number:	045-17109	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Culverts				
Gravel						
				Material Handling And Spill Prevention		
Rip Rap						
Compaction						
		Gravel				
Sediment Traps						
		Ditches				
Check Dams						
Berms						
Ditches						

Comment: Unable to inspect all Stormwater BMPs due to snow cover. Corrective Action from FIR #708900861 remains in effect.

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 07/11/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708303215	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6829689">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6829689</a>