

## Inspection Photos

Location Name: TEP Rocky Mountain LLC FEDERAL 0-4-7-94-W Pad

Location # 334848



Photo # 6172 From entrance to location



Photo # 6173 From entrance to location

# Inspection Photos

Location Name: TEP Rocky Mountain LLC FEDERAL 0-4-7-94-W Pad

Location # 334848



Photo # 6174 Location



Photo # 6175 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC FEDERAL 0-4-7-94-W Pad

Location # 334848



Photo # 6176 Location



Photo # 6177 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC FEDERAL 0-4-7-94-W Pad

Location # 334848



Photo # 6178 Location



Photo # 6179 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC FEDERAL 0-4-7-94-W Pad

Location # 334848



Photo # 6180 Location



Photo # 6181 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC FEDERAL 0-4-7-94-W Pad

Location # 334848



Photo # 6182 Location



Photo # 6183 PRV vent line does not comply with CECMC pressure safety device rules