

Final Reclamation and Stormwater Inspection

Date: 01/02/2025

Operator: STELBAR OIL CORP INC - 82470

Location ID: 317293

Inspection Document #: 708201894

Washington County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Photo 1. Eastern access road entrance appears to be progressing towards reclamation standards and regulations.



Photo 2. Portions of the access road east of the former location do not appear to have been reclaimed and require additional reclamation activities.



Photo 3. Access road entrance west of the former location requires additional work to contour and grade the road to match the existing grade/topography. Red line approximates current grade of access road.



Photo 4. Former meter shed west of the location does not appear to be progressing towards reclamation standards and regulations with evidence of undesirable vegetation and non-uniform vegetation cover.

Inspection Photos
Location Name: Price #9
Location ID: 317293



Photo 5. Continued from previous photo, facing southeast. See comments in Photo 4.



Photo 6. Taken from the southwest corner of the former location, near the separator. The area around the former separator requires additional reclamation activities as evidence of non-uniform vegetation resulting in bare soil was observed.



Photo 7. Taken from the northwest corner of the location, facing east. Portions of the reclaimed location appear to be progressing towards reclamation standards.



Photo 8. Taken from the northeast corner of the location, facing southwest. Portions of the reclaimed location appear to be progressing towards reclamation standards.



Photo 9. Taken from the southeast corner of the location, facing northwest. Portions of the reclaimed location appear to be progressing towards reclamation standards.