

# Inspection Photos

12/31/2024

**Operator:** ANSCHUTZ EXPLORATION CORP -  
3104

**Location ID:** 430927

**Inspection Doc:** 718100144

Rio Blanco County, CO

Aaron Trujillo  
Western Reclamation Work Lead  
ECMC



**COLORADO**


**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



**Photo 1:** Photos taken from the interim areas on the south end of the Location, and from the secondary access road along the northeast end of the Location. Additional reclamation efforts have been performed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



**Photo 2:** Anchors on Location have been marked pursuant to 1003.a requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**


Department of Natural Resources



## Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



**Photo 3:** Photos taken from equipment on the northeast end of the Location. Spills/leaking from equipment have continued. Operator has precariously placed a bucket beneath equipment to capture fluids; this is not proper management of E&P waste; buckets could easily be knocked over; fluids require removal and proper disposal and equipment maintained pursuant to 608.e requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



**Photo 4:** Continue from photo 3. Photos show spills/leaks have continued at equipment resulting in spills onto the surface of the Location/Pad.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



December 31, 2024



December 31, 2024

**Photo 5:** Photos taken from equipment on the north end of the Location. Spills/leaking from equipment have continued. Operator has precariously placed a bucket beneath equipment to capture fluids; this is not proper management of E&P waste; buckets could easily be knocked over; fluids require removal and proper disposal and equipment maintained pursuant to 608.e requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



December 31, 2024



December 31, 2024

**Photo 6:** Unused equipment stored on Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



December 31, 2024

**Photo 7:** Unused equipment stored on Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources