

KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310



Tank battery signs



Debris

KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310



Debris



Debris

KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310




Debris



When sign is replaced additional information is required

**KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310**



**Equipment leak and staining**

**Equipment leak and staining**

KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310



Debris



Debris

**KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310**



**Weeds**



**Erosion and soil migration**

**KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310**




**Erosion and soil migration**

**Erosion and soil migration**

KT Resources LLC  
 Ant Hill Unit 19-44  
 Location ID: 316310



Relief vents missing caps



Calibration overdue

**KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310**



**Location from West corner**



**Location from South corner**

**KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310**



**Location from East corner**



**Location from North corner and entrance**