

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/08/2025

Submitted Date:

01/11/2025

Document Number:

708905447

**FIELD INSPECTION FORM**

Loc ID 334388 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: 2094435

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

23 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297765	WELL	PR	04/01/2024	GW	045-16960	JOHNSON FED. 5-10C	PR
297766	WELL	PR	04/01/2024	GW	045-16961	JOHNSON 5-02B	PR
297767	WELL	PR	04/01/2024	GW	045-16962	JOHNSON FED. 5-15B	PR

**General Comment:**

[CECMC Inspection Report Summary](#)  
On 01/08/2025 at approximately 14:21 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC JOHNSON 05-07 pad. Location # 334388 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area. Location is approximately 498 yards from West Mamm Creek. While there, I observed normal production operations.  
  
This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
	Type Access		
comment:			
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:
	Type OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
	Type BATTERY		
Comment:			
Corrective Action:			Date:
	Type CONTAINERS		
Comment:	Chemical tank		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
	Type OTHER		
Comment:	Pig station - pipe rail fence		
Corrective Action:			Date:
	Type OTHER		
Comment:	Chemical tank - hog panels		
Corrective Action:			Date:

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical tank Equipment not listed in FORM 2A or FORM 4 SUNDRY/not in compliance with CECMC rules If operator remains out of compliance corrective action may be issued in future inspections.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 5		
Comment:	Marked		
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:	Taylor plugs located on bradenheads, bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:	Equipment not listed in FORM 2A or FORM 4 SUNDRY/not in compliance with CECMC rules If operator remains out of compliance corrective action may be issued in future inspections.		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,

<b>Comment:</b>	Tank not listed in FORM 2A or FORM 4 SUNDRY/not in compliance with CECMC rules				
	If operator remains out of compliance corrective action may be issued in future inspections.				
<b>Corrective Action:</b>					<b>Date:</b>
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)	500 gal				
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
<b>Comment:</b>	Limited inspection of secondary containment due to snow				
	Centralized containment				
<b>Corrective Action:</b>					<b>Date:</b>
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	400 BBLs	STEEL AST		,
<b>Comment:</b>	Tanks equipped with telemetry				
<b>Corrective Action:</b>					<b>Date:</b>
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
<b>Comment:</b>	Limited inspection of secondary containment due to snow				
	Centralized containment				
<b>Corrective Action:</b>					<b>Date:</b>
<b>Venting:</b>					
Yes/No	NO				
<b>Comment:</b>					
<b>Corrective Action:</b>					<b>Date:</b>
<b>Flaring:</b>					
Type					
<b>Comment:</b>					
<b>Corrective Action:</b>					<b>Date:</b>

**Inspected Facilities**

Facility ID: 297765 Type: WELL API Number: 045-16960 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 297766 Type: WELL API Number: 045-16961 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 297767 Type: WELL API Number: 045-16962 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Retention Ponds						
		Culverts				
		Ditches				
Berms						
Ditches						
Compaction						
		Compaction				
				Material Handling And Spill Prevention		Chemical tank containment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
Please refer to Equipment & Tanks & Berms for comments	smelserw	01/11/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708905448	Inspection 708905447 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6872233">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6872233</a>
708905449	Inspection 708905447 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6872234">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6872234</a>