

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/08/2025

Submitted Date:

01/11/2025

Document Number:

698602951**FIELD INSPECTION FORM**Loc ID 337748 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**18 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288459	WELL	PR	12/14/2006	GW	125-10554	SALVADOR 14-28 5N46W	PR

**General Comment:**Routine Inspection.

<b>Location</b>				
<b><u>Lease Road:</u></b>				
Type	Access			
comment:	Two track off maintained County Road.			
Corrective Action				Date:
Overall Good: <input type="checkbox"/>				
<b><u>Signs/Marker:</u></b>				
Type	WELLHEAD			
Comment:	Lease sign at wellhead location.			
Corrective Action:				Date:
Type	BATTERY			
Comment:	Lease sign posted at remote Gas Meter Run.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Emergency contact information posted on Lease sign.			
Corrective Action:				Date: _____
<b><u>Good Housekeeping:</u></b>				
Type	UNUSED EQUIPMENT			
Comment:	Chemical Tank and Electric Injection Pump noted inside wellhead fencing.			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
<b><u>Spills:</u></b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b><u>Fencing/:</u></b>				
Type	WELLHEAD			
Comment:	Stock panel fencing around surface equipment at well location.			
Corrective Action:				Date:
Type	OTHER			
Comment:	Stock panel fencing around surface equipment at remote gas metering location.			
Corrective Action:				Date:
<b><u>Equipment:</u></b>				
				corrective date
Type: Other	# 1			
Comment:	Shared Remote Gas Meter Shed.			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Pump Jack Power and Control Panel.			

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located on CR 55 & CR S at shared gathering location. Gas Meter Run. Chart in Meter Box dated 1-2-25. Meter Calibration/Test Log dated 10-29-24. Well Inlet Valve open. Gas Outlet Valve open.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Chemical Tank and Electric Injection Pump. Not connected.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric Motor.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Pump Jack welded steel pipe base.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve closed. Casing valve open.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	288459	Type:	WELL	API Number:	125-10554	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Rods and tubing in wellbore. Tubing valve closed. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.  Electronic Well File reflects last Production/Status reported 10/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.								
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698602974	Inspection photos.	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6872406">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6872406</a>