

Inspection Photos

Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 7854 From entrance to location



Photo # 7855 From entrance to location

Inspection Photos

Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad

Location #: 334755




Photo # 7856 Location

Photo # 7857 Location

Inspection Photos

Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Jan 9, 2025 at 1:50:50 PM
CO



Jan 9, 2025 at 1:53:11 PM
CO

Photo # 7858 Location

Photo # 7859 Location

Inspection Photos

Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 7860 Location



Photo # 7861 Location

Inspection Photos
Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad
Location #: 334755



Photo # 7862 Location



Photo # 7863 Location

Inspection Photos
Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad
Location #: 334755



Photo # 7864 Location

Photo # 7865 Location

Inspection Photos

Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 7866 Location



Photo # 7867 Location

Inspection Photos
Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad
Location #: 334755



Photo # 7868 Location



Photo # 7869 Location

Inspection Photos

Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 7870 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 7871 PRV vent line does not comply with CECMC pressure safety device rules