

**Inspection Photos**  
**Location Name: QB Energy GMU 23-14 (C26NW) Pad**  
**Location #: 335163**



Jan 9, 2025 at 12:43:16 PM  
CO



Jan 9, 2025 at 12:43:21 PM  
CO

**Photo # 7677 From entrance to location**

**Photo # 7678 From entrance to location**

# Inspection Photos

Location Name: QB Energy GMU 23-14 (C26NW) Pad  
Location #: 335163



Photo # 7679 Location

Photo # 7680 Location

**Inspection Photos**  
**Location Name: QB Energy GMU 23-14 (C26NW) Pad**  
**Location #: 335163**



**Photo # 7681 Location**



**Photo # 7682 Location**

Inspection Photos  
Location Name: QB Energy GMU 23-14 (C26NW) Pad  
Location #: 335163



Photo # 7683 Location



Photo # 7684 Location

Inspection Photos  
Location Name: QB Energy GMU 23-14 (C26NW) Pad  
Location #: 335163



Photo # 7685 Location

Photo # 7686 Location

**Inspection Photos**  
**Location Name: QB Energy GMU 23-14 (C26NW) Pad**  
**Location #: 335163**



**Photo # 7687 Location**



**Photo # 7688 Location**

**Inspection Photos**  
**Location Name: QB Energy GMU 23-14 (C26NW) Pad**  
**Location #: 335163**



**Photo # 7689 Location**



**Photo # 7690 Location**

**Inspection Photos**  
**Location Name: QB Energy GMU 23-14 (C26NW) Pad**  
**Location #: 335163**



**Photo # 7691 Location**



**Photo # 7692 Staining in secondary containment**

**Inspection Photos**  
**Location Name: QB Energy GMU 23-14 (C26NW) Pad**  
**Location #: 335163**



**Photo # 7693 PRV vent line does not comply with CECMC  
pressure safety device rules**