

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/06/2025

Submitted Date:

01/13/2025

Document Number:

710100342

FIELD INSPECTION FORM

Loc ID: 484289
Inspector Name: Anderson, Laurel
On-Site Inspection:
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Robinson, Taylor		taylor.robinson@state.co.us	
Metz, Collin		collin.metz@state.co.us	
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248152	WELL	SI		GW	123-15950	HSR-EDDINGTON 9-3	SI
328405	LOCATION	AC			-	HSR-EDDINGTON-63N66W 3NESE	EI
484290	TANK BATTERY	AC	04/18/2023		-	Eddington 3-3N-66W NESE TankBattery	EI

General Comment:

ECMC Environmental Inspection of the following Kerr McGee (Operator) facilities:
API 05-123-15950 HSR-EDDINGTON #9-3
TANK BATTERY Facility ID 484290 - Eddington 3-3N-66W NESE TankBattery
LOCATION ID 328405 - HSR-EDDINGTON-63N66W3NESE
Remediation Project No 30125 (CL)

Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no Operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Current site status:

-Weeds
-No final reclamation appears to have been conducted along flowline path from the HSR-EDDINGTON #9-3 wellhead to the separator at the Eddington 3-3N-66W NESE Tank Battery.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment: Weeds throughout tank battery and along former off-location flowline.

Corrective Action: Comply with Rule 606.

Date: 01/27/2025

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 248152 Type: WELL API Number: 123-15950 Status: SI Insp. Status: SI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 328405 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 484290 Type: TANK API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710100343	Photo Documentation	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6873629