

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Lantz/SG 44-23

Location ID: 429938

Date: 01/8/2025



Photo # 2359 Entrance to location




Photo # 2401 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Lantz/SG 44-23

Location ID: 429938

Date: 01/8/2025



Photo # 2360 Location



Photo # 2380 Location

Inspection Photos
Location: TEP ROCKY MOUNTAIN LLC Lantz/SG 44-23
Location ID: 429938
Date: 01/8/2025



Photo # 2397 Location



Photo # 2399 Location



Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Lantz/SG 44-23

Location ID: 429938

Date: 01/8/2025



Photo # 2411 NE corner of location



Photo # 2412 NW corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Lantz/SG 44-23

Location ID: 429938

Date: 01/8/2025



Photo # 2413 SW corner of location



Photo # 2414 SE corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Lantz/SG 44-23

Location ID: 429938

Date: 01/8/2025



Photo # 2386 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 2394 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Lantz/SG 44-23

Location ID: 429938

Date: 01/8/2025



Photo # 2405 Open ended load line



Photo # 2406 Open ended load line

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Lantz/SG 44-23

Location ID: 429938

Date: 01/8/2025



Photo # 2407 Open ended load line



Photo # 2409 Open ended load line

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Lantz/SG 44-23

Location ID: 429938

Date: 01/8/2025



Photo # 2415 Stained soil

