

Inspection Photos

Location: Grouse 13-36

Location ID: 307865

API # 05-071-07087




Photo 1 –Well placard

Photo 2 – Wellhead spill source area



Inspection Photos
Location: Grouse 13-36
Location ID: 307865
API # 05-071-07087




Photo 3 – Leaking valve on gathering line



Photo 4 – Spill path looking northeast

Inspection Photos
Location: Grouse 13-36
Location ID: 307865
API # 05-071-07087



Photo 5 – Spill Path



Photo 6 – Spill Path

Inspection Photos
Location: Grouse 13-36
Location ID: 307865
API # 05-071-07087



Photo 7 – Culvert in spill path, direction change



Photo 8 – Spill path, dry gully

Inspection Photos
Location: Grouse 13-36
Location ID: 307865
API # 05-071-07087



Photo 9 – Spill end, entering main ravine



Photo 10 – Main ravine looking northeast, down slope

Inspection Photos
Location: Grouse 13-36
Location ID: 307865
API # 05-071-07087



Photo 11 – Main ravine, looking southwest, up slope from spill entry



Photo 12 – Delilah 042 A discharge, Permit # COG-900006

Inspection Photos
Location: Grouse 13-36
Location ID: 307865
API # 05-071-07087



Photo 13 – Delilah 042 A discharge, Permit # COG-900006



Photo 14 – Looking northeast, ravine up slope from pond

Inspection Photos
Location: Grouse 13-36
Location ID: 307865
API # 05-071-07087



Photo 15 – Delilah 042 A discharge, Pond overflow



**Photo 16 – Delilah 042 A discharge, Pond overflow
down slope of pond**

Inspection Photos
Location: Grouse 13-36
Location ID: 307865
API # 05-071-07087



Photo 17 – looking northeast, ravine below Delilah 042 A outfall



Photo 18 – looking northeast, ravine below Delilah 042 A outfall