

Inspection Photos

January 13th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325965

Inspection Document #: 714001698

La Plata County, CO

Township: SESE 28 35N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lobato A1
Location ID: 325965



1/13/25
253° W



1/13/25
278° W

Photo 1. View of well pad taken from the access point facing center.

Inspection Photos
Location Name: Lobato A1
Location ID: 325965



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Vegetation encroaching on well head, remove combustible material from active equipment.

API #: 067-07248

Inspection Photos
Location Name: Lobato A1
Location ID: 325965

1/13/25
99° E



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Unused fencing equipment stored in the southern interim reclamation area.

API #: 067-07248

Inspection Photos
Location Name: Lobato A1
Location ID: 325965

1/13/25
144° SE



Photo 4. Stormwater BMPs/wattles installed in the southern portion of the location are not longer functioning, erosion persists.

Inspection Photos
Location Name: Lobato A1
Location ID: 325965

1/13/25
315° NW



Photo 5. Label at separator is deteriorating, future maintenance is advised.

Inspection Photos
Location Name: Lobato A1
Location ID: 325965



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Reference area composed of Smooth Brome, Gambel Oak and Blue Grama.

API #: 067-07248