

**KT Resources LLC  
Fee-62N96W 31SWW  
Location ID: 336391**



**Displayed well sign**



**When replaced additional information is required**

KT Resources LLC  
Fee-62N96W 31SWSW  
Location ID: 336391



Replace when damaged



Oily waste from leaking valve

KT Resources LLC  
Fee-62N96W 31SWSW  
Location ID: 336391





**Debris**



**Vent missing cap**

KT Resources LLC  
 Fee-62N96W 31SWSW  
 Location ID: 336391



Calibration overdue

Calibration overdue

**KT Resources LLC  
Fee-62N96W 31SWSW  
Location ID: 336391**



**Location from Northeast corner**



**Location from Northwest corner**

**KT Resources LLC  
Fee-62N96W 31SWSW  
Location ID: 336391**



**Location from Southwest corner**



**Location from Southeast corner**