

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NESE

Location ID: 335170

Date: 1/15/2025



Location Overview – Photo #05959



Location – Photo #05961

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NESE

Location ID: 335170

Date: 1/15/2025



Location – Photo #05962


Location – Photo #05970

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NESE

Location ID: 335170

Date: 1/15/2025



Illegible Wellhead Sign – Photo #05960



Unused Equipment – Photo #05965

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NESE

Location ID: 335170

Date: 1/15/2025



**Stored Supplies – Photo #05967**



**Debris Pile Near Separators – Photo #05968**

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NESE

Location ID: 335170

Date: 1/15/2025



Open-Ended Lines – Photo #05963

Open-Ended Lines – Photo #05964

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NESE

Location ID: 335170

Date: 1/15/2025



Open-Ended Load Line – Photo #05971



Open-Ended Load Line – Photo #05972

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NESE

Location ID: 335170

Date: 1/15/2025



Open-Ended Manifold Line/Oily Waste – Photo #05974



Open-Ended Manifold Line/Oily Waste – Photo #05975