



Fencing is present but does not encompass entire excavation. Livestock tracks observed.




Fencing is present but does not encompass entire excavation.





Multiple flowlines/flowline risers exposed within excavation.



Multiple flowlines/flowline risers exposed within excavation.





Unlabeled soil stockpiled on location. Liner is discontinuous.





Stockpiled soil appears to have been mixed with berm material.






Holes/tears present in liner.





Holes/tears present in liner.




Holes/tears present in liner.






Stockpiled soil appears to have been mixed with berm material. Holes/tears present in liner.



Stockpiled soil appears to have been mixed with berm material.





Liner is discontinuous. Snow/water has accumulated.



Excavation remains open. Snow has accumulated.





Excavation remains open. Livestock tracks observed.

