

Inspection Photos

API: 061-06365

Operator: STRACHAN EXPLORATION INC

Inspection Date: 1/14/2025

County: KIOWA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward by the wellsite. The area along the road where hydrocarbon impacts were observed have been scrapped and removed.



Inspection Photos



Photo 2. Facing southeast toward the pump jack..



Inspection Photos



Photo 3. The plastic container at the pumpjack is broke and needs to be removed and disposed. Previous CA was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06365 | Date: 1/14/2025

Inspection Photos



Photo 4. There were workers onsite repairing a leak along the flowline. There were oil stained soils at red arrow that will need to be cleaned up.



Inspection Photos



Photo 5. South side of the location facing north. There is a pile of material which has hydrocarbon impacts stored with no liner or containment. This appears to be part of the impacted berm material.



Inspection Photos



Photo 6. Facing toward the two fiberglass tanks. There is no secondary containment around the tanks which should be empty and not in use without containment.



Inspection Photos



Photo 7. Facing toward the tank where spill had previously occurred. There are sampling bore holes shown at red arrow.



Inspection Photos



Photo 8. Facing adjacent to the tank. There are still hydrocarbon impacted soils around the entire tank which have not been cleaned up.



Inspection Photos



Photo 9. There are still impacted soils around the entire tank where spill had occurred. The tank will need to be removed to excavate and remove all of the impacted soils.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06365 | Date: 1/14/2025

Inspection Photos



Photo 10. Facing northwest at the location. The two large volume tanks have been removed. The remaining pipes and barrel will also need to be removed. This area will need to be reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06365 | Date: 1/14/2025

Inspection Photos



Photo 11. Facing at the north side of the location. The fence around the tank battery is inadequate to prevent livestock entry. The berm around the tank has been rebuilt.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06365 | Date: 1/14/2025

Inspection Photos



Photo 12. Facing northeast at the north side of the location.

