

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/15/2025

Submitted Date:

01/16/2025

Document Number:

708303316

FIELD INSPECTION FORMLoc ID 335200 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, CAERUS		ecmc.inspections@qb-energy.com	
Popejoy, Dusty		dusty.popejoy@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252	WELL	PR	12/01/2018	GW	045-15460	N. PARACHUTE MF02B C28 696	PR
253	WELL	PR	12/01/2018	GW	045-15461	N. PARACHUTE MF01A C28 696	PR
254	WELL	SI	11/01/2022	GW	045-15462	N. PARACHUTE MF01D C28 696	SI
255	WELL	PR	12/01/2018	GW	045-15463	N. PARACHUTE MF01C C28 696	PR
256	WELL	PR	05/01/2024	GW	045-15464	N. PARACHUTE MF02A C28 696	PR
258	WELL	PR	12/01/2018	GW	045-15465	N. PARACHUTE MF02D C28 696	PR
259	WELL	PR	12/01/2018	GW	045-15466	N. PARACHUTE MF01B C28 696	PR
260	WELL	PR	12/01/2018	GW	045-15467	N. PARACHUTE MF02C C28 696	PR
291912	WELL	PR	12/01/2018	GW	045-14553	N. PARACHUTE MF15A-21 C28 69	PR
291915	WELL	PR	12/01/2018	GW	045-14552	N. PARACHUTE MF10A-21C28 696	PR
291916	WELL	PR	12/01/2018	GW	045-14551	N. PARACHUTE MF10B-21C28 696	PR
291918	WELL	PR	12/01/2018	GW	045-14550	N. PARACHUTE MF10C-21 C28 69	PR
291920	WELL	PR	12/01/2018	GW	045-14549	N. PARACHUTE MF10D-21 C28 69	PR
292039	WELL	PR	12/01/2018	GW	045-14554	N. PARACHUTE MF15B-21C28696	PR

293694	WELL	PR	12/01/2018	GW	045-15108	N. PARACHUTE MF15C-21 C28 69	PR
293695	WELL	TA	05/01/2021	GW	045-15109	N. PARACHUTE MF16C-21 C28 69	PA

General Comment:

CECMC Inspection Report Summary

On 1/15/2025 at approximately 13:30, Compliance Inspector Matthew Morris conducted an on-site inspection at CAERUS PICEANCE LLC, N. PARACHUTE-66S96W/28NENW at Location ID #335200 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

1) Unused equipment on location poses a wildlife entry hazard
2) Open-ended hose near gas meters

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970)285-2615

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment near wellheads. Unused equipment poses a wildlife entry hazard.		
Corrective Action:	Remove unused equipment to comply with Rule 606.	Date:	01/23/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Gas meter/gas lift housing protected by concrete barriers.		
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 3		corrective date
Comment:	Chemical tanks		
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 2		
Comment:	Mobile separators		
Corrective Action:		Date:	
Type: Gas Meter Run	# 16		
Comment:	Open-ended hose located near gas meters pose a wildlife entry hazard.		
Corrective Action:	Secure equipment to comply with Rule 608.e.	Date:	01/23/2025
Type: Gas Meter Run	# 16		
Comment:	Gas lift		
Corrective Action:		Date:	
Type: Plunger Lift	# 15		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Line heaters		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Wildlife screen installed on produced water tank		
Corrective Action:		Date:	
Type: Bradenhead	# 15		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:	Tank is showing signs of corrosion. No leaks at time of inspection.				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	80 bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO	
Comment:		

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 252 Type: WELL API Number: 045-15460 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 253 Type: WELL API Number: 045-15461 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 254 Type: WELL API Number: 045-15462 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In☐ Temporarily AbandonedReminder: Comment: Last produced October 2022 per production report.Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 255 Type: WELL API Number: 045-15463 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 256 Type: WELL API Number: 045-15464 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 258 Type: WELL API Number: 045-15465 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 259 Type: WELL API Number: 045-15466 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 260	Type: WELL	API Number: 045-15467	Status: PR	Insp. Status: PR
------------------	------------	-----------------------	------------	------------------

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291912	Type: WELL	API Number: 045-14553	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291915	Type: WELL	API Number: 045-14552	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291916	Type: WELL	API Number: 045-14551	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291918	Type: WELL	API Number: 045-14550	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291920	Type: WELL	API Number: 045-14549	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 292039	Type: WELL	API Number: 045-14554	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293694	Type: WELL	API Number: 045-15108	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well			
Comment:			
Corrective Action:			Date: <div></div>

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	293695	Type:	WELL	API Number:	045-15109	Status:	TA	Insp. Status:	PA
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Tracking Pad				
		Ditches				
Berms						
		Gravel				
Compaction						
Gravel						
		Compaction				
				Material Handling And Spill Prevention		

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708303317	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6878684