

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/13/2025

Submitted Date:

01/18/2025

Document Number:

698603004

FIELD INSPECTION FORMLoc ID 336750 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278965	WELL	PR	07/26/2005	GW	125-09368	JOSH 13-8 4N46W	PR

General Comment:

Routine Inspection.

Location				
Lease Road:				
Type	Access			
comment:	Two track off maintained County Road. Active agricultural cropland with seasonal access to well location.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Lease sign at wellhead location.			
Corrective Action:				Date:
Type	BATTERY			
Comment:	Lease sign posted at remote Gas Meter Run.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Emergency contact information posted on Lease sign.			
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	OTHER			
Comment:	Stock panel fencing around surface equipment at remote gas metering location.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Welded steel tube barrier.			
Corrective Action:				Date:
Equipment:				
Type: Gas Meter Run	# 1			corrective date
Comment:	Remote Gas Meter Run located on CR 52 & CR Q at shared gathering location. Digital Gas Meter Run. Meter Calibration/Test Log dated 3-12-24. Well Inlet Valve open. Gas Outlet Valve open. ** Meter calibration log reflects incorrect well API number. Log API reflects 05-125-10813 and should be 05-125-09368. **			
Corrective Action:				Date:
Type: Other	# 1			
Comment:	Shared Remote Gas Meter Shed.			
Corrective Action:				Date:

Type: Dehydrator	# 1		
Comment:	Dehydrator (Drip Bottle) on gas meter run inlet.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	Flowline riser at wellhead with valve and plug.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing production. Rods and tubing removed from the wellbore. Casing valve open.		
Corrective Action:		Date:	
Type: Vertical Separator	# 0		
Comment:	Removed.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	278965	Type:	WELL	API Number:	125-09368	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open. Electronic Well File reflects last Production/Status reported 11/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.								
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698603045	Inspection photos.	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6881217