

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/13/2025

Submitted Date:

01/18/2025

Document Number:

698603007**FIELD INSPECTION FORM**Loc ID 304652 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269774	WELL	PR	12/08/2003	GW	125-08813	KORF 4-25	PR

General Comment:Routine Inspection.

Location					
Lease Road:					
Type	Access				
comment:	Two track off maintained County Road. Active agricultural cropland with seasonal access to well location.				
Corrective Action	L				Date:
Overall Good: <input type="checkbox"/>					
Signs/Marker:					
Type	BATTERY				
Comment:	Lease sign posted at remote Gas Meter Run. Emergenct contact information is incorrect.				
Corrective Action:	Install sign to comply with Rule 605.e.				Date: 02/19/2025
Type	WELLHEAD				
Comment:	Lease sign at wellhead location. Lease sign is incorrect and shows Rosewood Resources Inc as operator and does not have correct emergency contact information.				
Corrective Action:	Install sign to comply with Rule 605.a.				Date: 02/19/2025
Emergency Contact Number:					
Comment:	Emergency contact information posted at both the remote battery and well location has the old operator information posted.				
Corrective Action:	Install sign to comply with Rule 605.a.				Date: 02/19/2025
Good Housekeeping:					
Type	UNUSED EQUIPMENT				
Comment:	Removed Pump Jack drive belt guard noted inside wellhead fencing. Stock panel laying on ground at well location.				
Corrective Action:					Date:
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	WELLHEAD				
Comment:	Stock panel fencing around surface equipment at well location.				
Corrective Action:					Date:
Equipment:					
				corrective date	
Type: Gas Meter Run	# 1				
Comment:	Remote Gas Meter Run located on CR 56 & Access. Gas Meter Run. Chart in Meter Box dated 1-2-25. Meter Calibration/Test Log dated 10-14-24. Well Inlet Valve open. Gas Outlet Valve open.				
Corrective Action:					Date:
Type: Pump Jack	# 1				
Comment:					
Corrective Action:					Date:

Type: Other	# 1		
Comment:	Pump Jack welded steel pipe base.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Remote Gas Meter Shed.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve closed. Casing valve open.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric Motor. Disconnected at time of inspection.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Pump Jack Power and Control Panel.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	269774	Type:	WELL	API Number:	125-08813	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Rods and tubing in wellbore. Tubing valve closed. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open. Electronic Well File reflects last Production/Status reported 11/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.								
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698603048	Inspection photos.	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6881366