

Inspection Photos

January 13th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 326147

Inspection Document #: 714001706

La Plata County, CO

Township: SENW 26 35N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Huber Lobato 1-26
Location ID: 326147



Photo 1. View of well pad taken from the access point facing center.

Inspection Photos
Location Name: Huber Lobato 1-26
Location ID: 326147



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of large tracks running through the northern interim reclamation area.

API #: 067-07551

Inspection Photos
Location Name: Huber Lobato 1-26
Location ID: 326147



Photo 3. View of stained soils at the pump jack/muffler.

Inspection Photos
Location Name: Huber Lobato 1-26
Location ID: 326147



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of trash on the northern edge of the pad.

API #: 067-07551

Inspection Photos
Location Name: Huber Lobato 1-26
Location ID: 326147



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area composed of Pine, Gambel Oak and Smooth Brome.

API #: 067-07551