

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404069550

Date Received:
01/24/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

.

rbucogccinspectionreports@chevron.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708201917

Inspection Date: 01/08/2025

FIR Submit Date: 01/08/2025

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 322808

Location Name: S.L.W. RANCH-65N64W Number: 10NESE County: _____

Qtrqtr: NESE Sec: 10 Twp: 5N Range: 64W Meridian: 6

Latitude: 40.413060 Longitude: -104.529660

FACILITY - API Number: 05-123- -00 Facility ID: 322808

Facility Name: S.L.W. RANCH-65N64W Number: 10NESE

Qtrqtr: NESE Sec: 10 Twp: 5N Range: 64W Meridian: 6

Latitude: 40.413060 Longitude: -104.529660

CORRECTIVE ACTIONS:

1 CA# 201565

Corrective Action: Perform reclamation in accordance with Rule 1004 to remove all equipment from disturbance areas.

Date: _____

Response: CA COMPLETED

Date of Completion: 01/24/2025

Operator Comment: Complying with 1004 Rule. Phillips 66/DCP has multiple 3 inch and 4 inch lines coming and going out of the valve set. The piping is gathering and transporting gas from other producing sites in the area. . Emailed Dylan mapping due to website would not allow me label my photos

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Complying with 1004 Rule. Phillips 66/DCP has multiple 3 inch and 4 inch lines coming and going out of the valve set. The piping is gathering and transporting gas from other producing sites in the area. Emailed Dylan mapping due to website would not allow me label my photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff White

Signed:

Title: HSE

Date: 1/24/2025 2:34:47 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files