

Inspection/Audit Photos

Location: VISION ENERGY LLC USA-69S98W/18NESW (USA 1-18 JC)

Location ID: 312548

Date: 01/23/2025



Jan 23, 2025 at 11:15:00 AM
+39.269831,-108.373043 ±7.84m
De Beque



Jan 23, 2025 at 12:22:02 PM
+39.269968,-108.372880 ±6.39m
De Beque

VISION ENERGY, LLC
USA 1-18 JC TANK BATTERY
NESW SEC. 18 T9S - R98W
MESA COUNTY, CO
EMERGENCY CONTACT: 970-563-0082
LEASE# COC12645A API# 05-077-08493

Photo # 3202 Entrance to location

Photo # 3251 Tank battery sign lacks public road used to access location/not in compliance with CECMC rules

Inspection/Audit Photos

Location: VISION ENERGY LLC USA-69S98W/18NESW (USA 1-18 JC)

Location ID: 312548

Date: 01/23/2025



Photo # 3203 Location



Photo # 3204 Location

Inspection/Audit Photos

Location: VISION ENERGY LLC USA-69S98W/18NESW (USA 1-18 JC)

Location ID: 312548

Date: 01/23/2025



Photo # 3207 Location



Photo # 3219 Location - Weeds/undesirable plant species near production equipment causing a fire hazard

Inspection/Audit Photos

Location: VISION ENERGY LLC USA-69S98W/18NESW (USA 1-18 JC)

Location ID: 312548

Date: 01/23/2025



Photo # 3249 Location



Photo # 3288 NE corner of location

Inspection/Audit Photos

Location: VISION ENERGY LLC USA-69S98W/18NESW (USA 1-18 JC)

Location ID: 312548

Date: 01/23/2025



Jan 23, 2025 at 1:08:36 PM
+39.269987,-108.373112 ±3.04m
De Beque



Jan 23, 2025 at 1:10:09 PM
+39.269394,-108.372430 ±2.93m
De Beque

Photo # 3289 NW corner of location

Photo # 3290 SW corner of location

Inspection/Audit Photos

Location: VISION ENERGY LLC USA-69S98W/18NESW (USA 1-18 JC)

Location ID: 312548

Date: 01/23/2025



Photo # 3291 SE corner of location



Photo # 3209 Wildlife hazards

Inspection/Audit Photos

Location: VISION ENERGY LLC USA-69S98W/18NESW (USA 1-18 JC)

Location ID: 312548

Date: 01/23/2025



Photo # 3211 Wildlife hazard



Photo # 3221 Wildlife hazard

Inspection/Audit Photos

Location: VISION ENERGY LLC USA-69S98W/18NESW (USA 1-18 JC)

Location ID: 312548

Date: 01/23/2025



Photo # 3232 Unlined Pit #1 appears to have condensate in it with weeds/undesirable plant species



Photo #3237 Unlined Pit #1 appears to have condensate in it with weeds/undesirable plant species

Inspection/Audit Photos

Location: VISION ENERGY LLC USA-69S98W/18NESW (USA 1-18 JC)

Location ID: 312548

Date: 01/23/2025



Photo # 3242 Unlined Pit #2 with weeds/undesirable plant species



Photo # 3252 Tank labels contain inaccurate info/not in compliance with CECMC rules

Inspection/Audit Photos

Location: VISION ENERGY LLC USA-69S98W/18NESW (USA 1-18 JC)

Location ID: 312548

Date: 01/23/2025



Photo # 3254 Secondary containment is insufficient/does not comply with CECMC rules. Additionally weeds/undesirable plant species inside secondary containment have compromised the containment



Photo # 3262 Wildlife hazard

Inspection/Audit Photos

Location: VISION ENERGY LLC USA-69S98W/18NESW (USA 1-18 JC)

Location ID: 312548

Date: 01/23/2025



Photo # 3266 Open ended load line



Photo # 3269 Weeds/undesirable plant species near production equipment causing a fire hazard

Inspection/Audit Photos

Location: VISION ENERGY LLC USA-69S98W/18NESW (USA 1-18 JC)

Location ID: 312548

Date: 01/23/2025



Photo # 3275 Weeds/undesirable plant species near production equipment causing a fire hazard



Photo # 3284 Weeds/undesirable plant species near production equipment causing a fire hazard

Inspection/Audit Photos

Location: VISION ENERGY LLC USA-69S98W/18NESW (USA 1-18 JC)

Location ID: 312548

Date: 01/23/2025



Photo # 3285 Debris



Photo # 3286 Debris

Inspection/Audit Photos

Location: VISION ENERGY LLC USA-69S98W/18NESW (USA 1-18 JC)

Location ID: 312548

Date: 01/23/2025



Photo # 3293 Debris



Photo # 3294 Debris