

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/23/2025

Submitted Date:

01/24/2025

Document Number:

713400643**FIELD INSPECTION FORM**Loc ID 312548 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10770Name of Operator: VISION ENERGY LLCAddress: P O BOX 370City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**21 Number of Comments8 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
ENERGY, VISION		pbechtolt@maralexinc.com	
Benjamin Koch		bzkoch@blm.gov	
ENERGY, VISION		mollieo@maralexinc.com	
ENERGY, VISION		mrine20@maralexinc.com	
Toews, Wesley		wtoews@blm.gov	
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
112451	PIT				-	USA 1-18	
221891	WELL	PR	03/01/2021	GW	077-08493	USA 1-18 JC	SI

General Comment:

CECMC Inspection/Audit Report Summary

On 1/23/2025 at approximately 11:15 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at VISION ENERGY LLC USA-69S98W/18NESW (USA 1-18 JC) at Location ID #312548 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection/audit, the following compliance issues were observed:

1. Pits - Unlined pits on location that do not comply with CECMC rules with a CA date of 02/7/2025
2. Equipment - Open ended piping/wildlife hazard/available for entry by wildlife with a CA date of 01/31/2025
3. Equipment - Holes in separator buildings/wildlife hazard/available for entry by wildlife with a CA date of 01/31/2025
4. Equipment - Open ended load line with a CA date of 01/31/2025
5. Housekeeping - Weeds/undesirable plant species near production equipment causing a fire hazard with a CA date of 01/31/2025
6. Tanks and Berms - Secondary containment is insufficient/does not comply with CECMC rules with a CA date of 02/13/2025
7. Signs/Marker - Tank labels contain inaccurate info/not in compliance with CECMC rules with a CA date of 02/25/2025
8. Signs/Marker - Tank battery sign lacks public road used to access location not in compliance with CECMC rules with a CA date of 02/25/2025

A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location			
Lease Road:			
Type	Access		
comment:	Access		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Tank battery sign lacks public road used to access location/not in compliance with CECMC rules, refer to photos		
Corrective Action:	Comply with CECMC Signage rules		Date: 02/25/2025
Type	TANK LABELS/PLACARDS		
Comment:	Tank labels contain inaccurate info/not in compliance with CECMC rules, refer to photos		
Corrective Action:	Comply with CECMC Labeling rules		Date: 02/25/2025
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	970-563-0082		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris, refer to photos		
Corrective Action:			Date:
Type	WEEDS		
Comment:	Weeds/undesirable plant species near production equipment causing a fire hazard, refer to photos		
Corrective Action:	Comply with CECMC rules		Date: 01/31/2025
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Pipe rail fence		

Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Pipe rail fence		
Corrective Action:		Date:	
Type	PIT		
Comment:	Mesh		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Open ended piping/wildlife hazard/available for entry by wildlife, refer to photos		
Corrective Action:	Comply with CECMC wildlife rules	Date:	01/31/2025
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment. Bradenhead valve is accessible		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Open ended load line, refer to photos		
Corrective Action:	All load lines will be capped or plugged	Date:	01/31/2025
Type: Other	# 2		
Comment:	Holes in separator buildings/wildlife hazard/available for entry by wildlife, refer to photos		
Corrective Action:	Comply with CECMC wildlife rules	Date:	01/31/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

PRODUCED WATER	1	STEEL AST			
Comment: Tank not equipped with telemetry					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment: Secondary containment is insufficient/does not comply with CECMC rules. Additionally weeds/undesirable plant species inside secondary containment have compromised the containment, refer to photos					
Corrective Action: Comply with CECMC rules					Date: 02/13/2025
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	112451	Type:	PIT	API Number:	-	Status:		Insp. Status:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	221891	Type:	WELL	API Number:	077-08493	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned									
Reminder:									
Comment: Shut in									
Corrective Action:									
Date:									
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Berms				
Berms						
		Ditches				
Ditches						

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Type:

Lined: NO

Pit ID:

Lat:

Long:

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

2 unlined pits on location, 1 pit has a location ID & the 2nd pit on location does not have a location ID/does not appear to be in the CECMC database. Unable to locate permits for either pit in the CECMC database. Additionally 1 pit appears to have condensate in it. Weeds/undesirable plant species in both pits. Refer to photos

Corrective Action

Comply with CECMC rules & in addition also contact CECMC environmental protection Specialist John Heil to discuss observed compliance issues and closure of pits.

Date: 02/07/2025**Fencing:**Fencing Type: Wildlife

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:Netting Type: Mesh

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

ECMC Comments

Comment	User	Date
Please refer to Pits, Housekeeping, Equipment, Tanks and Berms & Signs/Marker for corrective actions.	popejoyd	01/24/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400646	Inspection-Audit Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6889532