

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/15/2025

Submitted Date:

01/15/2025

Document Number:

699506800**FIELD INSPECTION FORM**Loc ID 319935 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|---------------|---------------------------------|
| , | | cogcc@kpk.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 201933 | WELL | PR | 06/01/2021 | GW | 001-07337 | UPRR 24 PAN AM C 2 | PR |

General Comment:[There have been no changes to equipment on location since previous inspection.](#)

| Location | | | | |
|--|-------|---------------------------------------|--|------------------|
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Emergency Contact Number: | | | | |
| Comment: | | | | Date: _____ |
| Corrective Action: | | | | |
| Good Housekeeping: | | | | |
| Type | OTHER | | | |
| Comment: | | Trash on location needs to be removed | | |
| Corrective Action: | | Comply with rule 606 | | Date: 02/15/2025 |
| Overall Good: <input type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Venting: | | | | |
| Yes/No | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Flaring: | | | | |
| Type | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Inspected FacilitiesFacility ID: 201933 Type: WELL API Number: 001-07337 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 08/13/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|---|---------|------------|
| On 1/15/25 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- UPRR 42 PAN AM C 2 Company Name- KPK API- 05-001-07337 In Adams County Colorado. While there, I observed PR well During this inspection the following possible compliance issues were observed: Trash. Rule 606. 2/15/25 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report. | medinaj | 01/15/2025 |

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404062548 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6881330 |
| 699506801 | inspection pictures | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6881320 |