

Inspection Photos

Loc: 309327

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 1/24/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. There is erosion occurring along the access road which needs to be repaired and stabilized..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309327 | Date: 1/24/2025

Inspection Photos



Photo 2. Facing southwest along the access road. The culvert is filled in with sediment at this area.



Inspection Photos



Photo 3. Facing southwest along the access road. It appears the culvert may be filled in and stormwater causing erosion along the road side at this area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309327 | Date: 1/24/2025

Inspection Photos



Photo 4. Facing southwest toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309327 | Date: 1/24/2025

Inspection Photos



Photo 5. Facing east toward the fill slope. There are signs of erosion along the fill slope.

