

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/15/2025

Submitted Date:

01/28/2025

Document Number:

717100052

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
Rollins, Grace \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
Brown, Kari		kari.oakman@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
,		ECMCInspections@Oxy.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488858	SPILL OR RELEASE	CL	12/12/2024		-	HSR-Elton Miller 3-7A Flowline	EI
488862	SPILL OR RELEASE	CL			-	HSR-Elton Miller 3-7A Flowline	EI

**General Comment:**


ECMC Environmental Field Inspection Report Summary  
Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill IDs: 488858 and 488862  
Spill Name: HSR-Elton Miller 3-7A Flowline  
Remediation Project #: 35454  
Wellhead API #: 05-123-19611  
Reported Date of Discovery: 12/11/2024  
Date of Inspection: 01/15/2025

Spill is located within or adjacent to:  
-Bald Eagle Roost Site  
-Wetlands  
-100-year floodplain  
-Livestock rangeland

Current site status:  
-Excavations have been backfilled.  
-Wildlife observed.  
-Salt crusting observed along flowline path and throughout field.

See attached corrective actions. A Supplemental Form 27 is required.



**Inspected Facilities**

Facility ID: 488858 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 488862 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Remediation Project No. 35454 was created for the plugging and abandonment of the HSR-Elton Miller 3-7A wellhead and the removal of the associated flowline. The excavations associated with these spills have been backfilled. No environmental impacts were visible. Salt crusting observed along flowline path and throughout field. Quarterly reporting was required under Remediation Project No. 35454; the last Form 27 for this project was submitted 09/19/2024 (Document No. 403914801).

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation Project No. 35454.

Date: 02/11/2025

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100053	ECMC Photo Log - HSR-Elton Miller 3-7A Flowline	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892528">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892528</a>