

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/15/2025

Submitted Date:

01/28/2025

Document Number:

717100058**FIELD INSPECTION FORM**Loc ID 445907 Inspector Name: Rollins, Grace On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Brown, Kari		kari.oakman@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
,		ECMCInspections@Oxy.com	All Inspections
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488319	SPILL OR RELEASE	CL	10/16/2024		-	Miller FD 5&6-7A O SA	EI

General Comment:**ECMC Environmental Field Inspection Report Summary**

Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 488319

Spill Name: Miller FD 5&6-7A

Remediation Project #: 35788

Facility ID: 446839

Reported Date of Discovery: 10/14/2024

Date of Inspection: 01/15/2025

Spill is located within or adjacent to:

-Bald Eagle Roost Site HPH

-100-year floodplain

-Livestock rangeland

Current site status:

-Two excavation areas are surrounded by orange construction fencing.

-Wildlife protection equipment (netting) covers portions of the excavations.

-Excavations remain open with snow accumulation.

-Evidence of wildlife (tracks and scat) observed.

-Unnecessary equipment observed.

See attached corrective actions. A Supplemental Form 27 is required.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unnecessary equipment observed adjacent to the southwestern excavation area.		
Corrective Action:	Comply with Rule 606.		Date: 02/12/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Two excavation areas are surrounded by orange construction fencing. Bird netting covers portions of the excavations.		
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 488319 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: Location lies within the CPW Bald Eagle Roost Site High Priority Habitat. Wildlife protection equipment (netting) has been installed over portions of the open excavations. The excavation areas with netting appear to be those at which groundwater has been observed.

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities									
Facility ID:	488319	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental

Spills/Releases:

Type of Spill:

Estimated Spill Volume:

Comment:

Remediation Project No. 35788 was created for the decommissioning of the Miller FD 5&6-7A Facility. Two excavation areas are surrounded by orange construction fencing. Bird netting covers portions of the excavations. Excavations remain open with snow accumulation. Evidence of wildlife (tracks and scat) observed. Quarterly reporting was required under Remediation Project No. 35788; the last From 27 for this project was submitted 06/05/2024 (Document No. 403814867).

Corrective Action:

In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation Project No. 35788.

Date: 02/11/2025

Reportable:

GPS: Lat

Long

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

DWR Receipt Num:

Owner Name:

GPS :

Lat

Long

Field Parameters:

Sample Location:

Comment:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100059	ECMC Photo Log - Miller FD 5&6-7A	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892530