

**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



Unlabeled container



Oily waste and stained soil

**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



Debris



Open to wildlife

**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



Stained soil



Stained soil

**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



Stained soil



Location from the West