

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/22/2025

Submitted Date:

01/22/2025

Document Number:

708905558**FIELD INSPECTION FORM**Loc ID 334572 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**20 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
QB Energy		ecmc.inspections@qb-energy.com	
Toews, Wesley		wtoews@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211485	WELL	PR	10/16/2003	GW	045-07245	SAVAGE 1-34	PR
276681	WELL	PR	02/01/2013	GW	045-10511	SAVAGE FEDERAL 1-9A (R11)	PR
276682	WELL	SI	07/01/2024	GW	045-10510	SAVAGE FEDERAL 1-9D (R11)	SI

**General Comment:****CECMC Audit Report Summary**

On 01/22/2025 at approximately 14:00 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up audit at QB Energy SAVAGE 1-34 (R11) Pad.

Location # 334572 in Garfield County Colorado.

Please refer to audit 708905436 conducted on 01/07/2025, 2 of 3 previous corrective actions have been completed.

Location is within High Priority/NSO/Black Bear Habitat areas.

Location is within Rule 411a Surface Water Intermediate Buffer.

Location is approximately 400 yards from Beaver Creek.

While there, I observed normal production operations.

During this audit the following compliance issues were observed:

1. Equipment - Flowline heating insulation open ended/wildlife hazard with a CA date of 01/16/2025

A follow up on this site audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of audit report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Signs at separators		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign near entrance to location		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/>	Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 3		
Comment:	Pressure transducers located on bradenheads, bradenhead valves are accessible		

Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:	Summit Midstream		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:	Marked		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Flowline heating insulation open ended/wildlife hazard/available for entry by wildlife		
Corrective Action:	Comply with CECMC wildlife rules	Date:	01/16/2025

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient			
Comment:	Centralized containment				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLs	STEEL AST		,
Comment:	Tanks equipped with telemetry				
Corrective Action:					Date:

**Paint**

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:	Centralized containment			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211485	Type:	WELL	API Number:	045-07245	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	276681	Type:	WELL	API Number:	045-10511	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	276682	Type:	WELL	API Number:	045-10510	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:	<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:				
Comment:	Shut In								
	Last produced June 2024								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Compaction						
		Culverts				
Gravel						Sparse to none in some areas
		Compaction				

Comment: [Limited Stormwater audit due to snow](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Equipment for corrective action</a>	smelserw	01/22/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404066864	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6886412">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6886412</a>
708905559	Audit 708905558 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6886410">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6886410</a>
708905560	Audit 708905558 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6886411">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6886411</a>