

Inspection Photos

Location Name: McCall 42-09 1N46W

API Number: 125-12103



1. Lease sign at well location.



2. View of wellhead. Rods and Tubing are back in wellbore.

Inspection Photos
Location Name: McCall 42-09 1N46W
API Number: 125-12103



4. View of pump jack with horse head removed, Crew will be getting well set up to return to production.



5. View of rig at well location.