

Excavation area with metal fencing and soil stockpile visible.






Soil stockpile marked as "Topsoil Storage" on location; BMPs are adequate.







Metal fencing has been installed around the excavation. A pipeline marker is visible.




WGS84 $\pm 16\text{ft}$ 40.04532, -104.85398 $\Delta_{\pm 3\text{m}}^{\text{m}}$ 1512 $\triangle_{\pm 13}^{\circ, \text{T}}$ W274



ECMC
Environmental
Field Inspection 

Highum, Norden, Clark Facility
© 24-Jan-25 01:01:41 PM
ECMC Environmental Inspection

WGS84 $\pm 16\text{ft}$ 40.04537, -104.85403 $\Delta_{\pm 3\text{m}}^{\text{m}}$ 1513 $\triangle_{\pm 13}^{\circ, \text{T}}$ NW286




ECMC
Environmental
Field Inspection 

Highum, Norden, Clark Facility
© 24-Jan-25 01:01:51 PM
ECMC Environmental Inspection



Gray staining is visible on the excavation sidewalls in-situ.





WGS84
±16ft

40.04524, -104.85459

m
±3m

1512

°T
±13

N349



ECMC
Environmental
Field Inspection



Highum, Norden, Clark Facility
© 24-Jan-25 01:03:07 PM
ECMC Environmental Inspection

WGS84
±16ft

40.04524, -104.85459

m
±3m

1512

°T
±13

NW306



ECMC
Environmental
Field Inspection





Highum, Norden, Clark Facility
© 24-Jan-25 01:03:09 PM
ECMC Environmental Inspection

The western portion of the excavation was deepened in the area of recent Spill ID 489119 and will be addressed on a separate inspection.



An unmarked stockpile was visible west of the spill location; BMPs are adequate.





WGS84
±16ft

40.04514, -104.85414

m
±3m

1511

°T
±13

NW296



ECMC
Environmental
Field Inspection



Highum, Norden, Clark Facility
© 24-Jan-25 01:34:35 PM
ECMC Environmental Inspection