

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/23/2025

Submitted Date:

01/23/2025

Document Number:

718000025**FIELD INSPECTION FORM**Loc ID 439195 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10261Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLCAddress: 730 17TH ST STE 500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rogers, Brad		brogers@bayswater.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439193	WELL	PA	10/20/2023	OW	123-40341	WAAG 5	EI
439194	WELL	PA	10/18/2023	OW	123-40342	WAAG 1	EI
439196	WELL	PA	10/16/2023	OW	123-40343	WAAG 2	EI
439197	WELL	PA	02/12/2018	LO	123-40344	WAAG 3	EI
439198	WELL	PA	10/18/2023	OW	123-40345	WAAG 4	EI
439219	WELL	PA	12/27/2023	OW	123-40364	WAAG 7	EI

General Comment:ECMC Environmental Inspection, Remediation Project 34900

Environmental

Spill/Remediation:

Comment:

ECMC Environmental Inspection of Remediation Project 34900 for well P&A and flowline abandonment, and production facility decommissioning.

All wells were plugged in October 2023. Flowlines remain in place. Separators have been removed. Separator flowline and dumphine risers remain in place. All other equipment appears to remain in place.

Two buried vessels, and flowline risers and piping risers and manifolds not identified on the Proposed Soil Assessment Map included with the approved Initial Form 27. See attached photos for documentation of equipment.

Operator has not decommissioned production facility after fall harvest as proposed on the Supplemental Form 27 Document #403832364.

Corrective Action:

Operator shall commence execution of the approved Form 27 Site Investigation and Remediation Workplan as approved on Document #s 403729757 and 403832364. Operator shall also amend its workplan to collect soil samples for laboratory analysis at the buried vessels, and flowline risers and piping risers and manifolds not identified on the Proposed Soil Assessment Map included with the approved Initial Form 27.

Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404068404	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6887854
718000026	Waag North Photos 1-23-2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6887832