

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/30/2025

Submitted Date:

01/30/2025

Document Number:

715800614

**FIELD INSPECTION FORM**

Loc ID 318317 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Norton, Mathew		mnorton@kpk.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241097	WELL	PR	12/01/2017	GW	123-08885	SHELDON R. SICKLER 3	PR

**General Comment:**

[This is a Wellsite scout card audit followed by a field inspection.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate, Faded and will need to be replaced in the near future		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

**Good Housekeeping:**

Type	WEEDS		
Comment:	Dead vegetation around the location ROW and around the equipment		
Corrective Action:	Comply with Rule 606	Date:	02/13/2025

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	Fabricated angle iron		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Barb wire		
Corrective Action:		Date:	
Type	OTHER		
Comment:	ancillary equipment has 2 sets of fabricated steel pipe		
Corrective Action:		Date:	

**Equipment:**

Type		#	corrective date
Prime Mover		# 1	
Comment:	electric motor		
Corrective Action:		Date:	
Pump Jack		# 1	
Comment:			
Corrective Action:		Date:	
Ancillary equipment		# 1	
Comment:	electric panel, meter box & transformers		
Corrective Action:		Date:	

Type: Bradenhead	# 1	
Comment:	Plumbed to surface	
Corrective Action:		Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:



**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      On Thursday 1-30-2025 at approximately 1245 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card &amp; related forms followed by an onsite inspection:                      Operator: KP Kauffman                      Location # 318317                      API # 05-123-08885                      Well name: Sheldon R. Sickler 3                      County: Weld                      Weather: Cloudy &amp; clear                      Temp: 50*                      Location: Snow covered &amp; muddy                      While there, I observed a wellsite, PR at the time of inspection.                      During this inspection the following possible compliance issues were observed:                      606 housekeeping: CA date 2-13-2025.                      See attached photos.                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	revasr	01/30/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715800615	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6899082">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6899082</a>