

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/22/2025

Submitted Date:

01/27/2025

Document Number:

698603120**FIELD INSPECTION FORM**Loc ID 411781 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**22 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone        | Email                        | Comment |
|--------------|--------------|------------------------------|---------|
| Dolezal, Pat | 970-332-3585 | pat.dolezal@ownresources.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 301952      | WELL | PR     | 04/05/2010  | GW         | 125-11680 | MILLER 22-08 1N44W | PR          |

**General Comment:**

Routine Inspection.

**Location**

|                    |                                                                                                           |       |  |
|--------------------|-----------------------------------------------------------------------------------------------------------|-------|--|
| <b>Lease Road:</b> |                                                                                                           |       |  |
| Type               | Access                                                                                                    |       |  |
| comment:           | Two track off maintained County Road. Active agricultural cropland with seasonal access to well location. |       |  |
| Corrective ActionL |                                                                                                           | Date: |  |

Overall Good: ☐

|                      |                                                                                     |       |  |
|----------------------|-------------------------------------------------------------------------------------|-------|--|
| <b>Signs/Marker:</b> |                                                                                     |       |  |
| Type                 | TANK LABELS/PLACARDS                                                                |       |  |
| Comment:             | Content/Quantity/Hazard sign at produced water tank. Stickers are peeling off tank. |       |  |
| Corrective Action:   |                                                                                     | Date: |  |
| Type                 | BATTERY                                                                             |       |  |
| Comment:             | Lease sign posted at remote Gas Meter Run.                                          |       |  |
| Corrective Action:   |                                                                                     | Date: |  |
| Type                 | WELLHEAD                                                                            |       |  |
| Comment:             | Lease sign at wellhead location.                                                    |       |  |
| Corrective Action:   |                                                                                     | Date: |  |

Emergency Contact Number:

Comment: Emergency contact information posted on Lease sign.

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |                                                                                                                                                                                                                                                                             |       |  |
|--------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|--|
| Type               | WEEDS                                                                                                                                                                                                                                                                       |       |  |
| Comment:           | Dried weed and vegetation debris inside fencing at well location.                                                                                                                                                                                                           |       |  |
| Corrective Action: |                                                                                                                                                                                                                                                                             | Date: |  |
| Type               | OTHER                                                                                                                                                                                                                                                                       |       |  |
| Comment:           | Black poly pipe and electric line at well location. Pipe that was possibly used for conduit appears to have been struck and caught up in Ag equipment. The busted line should be removed and electric line needs to be clearly protected or marked to prevent reoccurrence. |       |  |
| Corrective Action: |                                                                                                                                                                                                                                                                             | Date: |  |

Overall Good: ☐

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |                                                                |       |  |
|--------------------|----------------------------------------------------------------|-------|--|
| <b>Fencing/:</b>   |                                                                |       |  |
| Type               | WELLHEAD                                                       |       |  |
| Comment:           | Stock panel fencing around surface equipment at well location. |       |  |
| Corrective Action: |                                                                | Date: |  |
| Type               | TANK BATTERY                                                   |       |  |

|                           |                                                                                                                                                                                                                      |          |                |         |                       |                 |
|---------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------------|---------|-----------------------|-----------------|
| Comment:                  | Stock panel fencing around surface equipment at remote tank battery and gas metering location.                                                                                                                       |          |                |         |                       |                 |
| Corrective Action:        |                                                                                                                                                                                                                      |          |                |         | Date:                 |                 |
| <b>Equipment:</b>         |                                                                                                                                                                                                                      |          |                |         |                       | corrective date |
| Type: Other               | # 1                                                                                                                                                                                                                  |          |                |         |                       |                 |
| Comment:                  | Remote Separator Shed. Roof damaged.                                                                                                                                                                                 |          |                |         |                       |                 |
| Corrective Action:        |                                                                                                                                                                                                                      |          |                |         | Date:                 |                 |
| Type: Other               | # 1                                                                                                                                                                                                                  |          |                |         |                       |                 |
| Comment:                  | Shared Remote Gas Meter Shed.                                                                                                                                                                                        |          |                |         |                       |                 |
| Corrective Action:        |                                                                                                                                                                                                                      |          |                |         | Date:                 |                 |
| Type: Dehydrator          | # 1                                                                                                                                                                                                                  |          |                |         |                       |                 |
| Comment:                  | Dehydrator (Drip Bottle) on gas meter run inlet.                                                                                                                                                                     |          |                |         |                       |                 |
| Corrective Action:        |                                                                                                                                                                                                                      |          |                |         | Date:                 |                 |
| Type: Gas Meter Run       | # 1                                                                                                                                                                                                                  |          |                |         |                       |                 |
| Comment:                  | Remote Gas Meter Run located on CR .3 & Access at shared gathering location. Gas Meter Run. Chart in Meter Box dated 1-2-25. Meter Calibration/Test Log dated 7-24-24. Well Inlet Valve open. Gas Outlet Valve open. |          |                |         |                       |                 |
| Corrective Action:        |                                                                                                                                                                                                                      |          |                |         | Date:                 |                 |
| Type: Flow Line           | # 1                                                                                                                                                                                                                  |          |                |         |                       |                 |
| Comment:                  | Flowline riser at wellhead with valve and plug.                                                                                                                                                                      |          |                |         |                       |                 |
| Corrective Action:        |                                                                                                                                                                                                                      |          |                |         | Date:                 |                 |
| Type: Ancillary equipment | # 1                                                                                                                                                                                                                  |          |                |         |                       |                 |
| Comment:                  | Wellhead. Casing production. Rods removed and tubing in the wellbore. Tubing valve open. Casing valve not connected.                                                                                                 |          |                |         |                       |                 |
| Corrective Action:        |                                                                                                                                                                                                                      |          |                |         | Date:                 |                 |
| Type: Flow Line           | # 1                                                                                                                                                                                                                  |          |                |         |                       |                 |
| Comment:                  | Flowline riser at remote gathering location with valve and plug.                                                                                                                                                     |          |                |         |                       |                 |
| Corrective Action:        |                                                                                                                                                                                                                      |          |                |         | Date:                 |                 |
| Type: Bradenhead          | # 1                                                                                                                                                                                                                  |          |                |         |                       |                 |
| Comment:                  | Bradenhead plumbed to surface.                                                                                                                                                                                       |          |                |         |                       |                 |
| Corrective Action:        |                                                                                                                                                                                                                      |          |                |         | Date:                 |                 |
| Type: Vertical Separator  | # 1                                                                                                                                                                                                                  |          |                |         |                       |                 |
| Comment:                  |                                                                                                                                                                                                                      |          |                |         |                       |                 |
| Corrective Action:        |                                                                                                                                                                                                                      |          |                |         | Date:                 |                 |
| <b>Tanks and Berms:</b>   |                                                                                                                                                                                                                      |          |                |         |                       |                 |
| Contents                  | #                                                                                                                                                                                                                    | Capacity | Type           | Tank ID | SE GPS                |                 |
| PRODUCED WATER            | 1                                                                                                                                                                                                                    | 200 BBLS | FIBERGLASS AST |         | 40.068460,-102.317660 |                 |
| Comment:                  | Shared battery is located at CR .3 and Access Trail. Remote gas meter is all so at this shared location.                                                                                                             |          |                |         |                       |                 |
| Corrective Action:        |                                                                                                                                                                                                                      |          |                |         | Date:                 |                 |
| <b>Paint</b>              |                                                                                                                                                                                                                      |          |                |         |                       |                 |
| Condition                 | Adequate                                                                                                                                                                                                             |          |                |         |                       |                 |

|                  |  |
|------------------|--|
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

Berms

|                    |                                                                                 |                     |                     |                  |
|--------------------|---------------------------------------------------------------------------------|---------------------|---------------------|------------------|
| Type               | Capacity                                                                        | Permeability (Wall) | Permeability (Base) | Maintenance      |
| Metal              | Adequate                                                                        | Walls Insufficient  | Base Insufficient   | Inadequate       |
| Comment:           | Containment is not lined and metal containment wall is rusted through at grade. |                     |                     |                  |
| Corrective Action: | Repair or install berms or other secondary containment devices per Rule 603.o.  |                     |                     | Date: 02/27/2025 |

Venting:

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

Flaring:

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities |                                                                                                                                                                                                                                                                                                |       |      |             |           |         |    |               |    |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 301952                                                                                                                                                                                                                                                                                         | Type: | WELL | API Number: | 125-11680 | Status: | PR | Insp. Status: | PR |
| Producing Well       |                                                                                                                                                                                                                                                                                                |       |      |             |           |         |    |               |    |
| Comment:             | Tubing valve open. Casing valve not connected. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.<br><br>Electronic Well File reflects last Production/Status reported 11/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is PR. |       |      |             |           |         |    |               |    |
| Corrective Action:   |                                                                                                                                                                                                                                                                                                |       |      |             |           |         |    | Date:         |    |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL                                                                                                                                                                     |
|--------------|----------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 404071293    | INSPECTION SUBMITTED | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892062">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892062</a> |
| 698603143    | Inspection photos.   | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892036">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892036</a> |