

Inspection Photos

ID: 321570

Operator: **MULL DRILLING COMPANY INC**

Inspection Date: 1/28/2025

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest toward the wellsite..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

ID:321570 | Date: 1/28/2025

Inspection Photos



Photo 2. Facing toward the pumpjack engine shed. There are stained soils shown at red arrows that need to be cleaned up..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:321570 | Date: 1/28/2025

Inspection Photos



Photo 3. There is oil stained soils inside the shed from the leaking pumpjack engine.

