

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/15/2025

Submitted Date:

01/28/2025

Document Number:

717100045**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 _____ Rollins, Grace _____ 2A Doc Num: _____

Operator Information:ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
,		ECMCInspections@Oxy.com	All Inspections
Brown, Kari		kari.oakman@state.co.us	
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488931	SPILL OR RELEASE	CL	12/27/2024		-	Windell 4-18A Wellhead	EG

General Comment:

ECMC Environmental Field Inspection Report Summary

Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 488931

Remediation Project #: 37053

Spill Name: Windell 4-18A Wellhead

Wellhead API #: 05-123-20649

Reported Date of Discovery: 12/26/2024

Date of Inspection: 01/15/2025

Spill is located within or adjacent to:

- Fort Lupton Municipality
- South Platte River
- Wetlands
- Bald Eagle Active Nest Site Half Mile / Bald Eagle Active Nest Site Qtr Mile
- Bald Eagle Roost Site
- Mule Deer Migration Corridor
- Mule Deer Winter Concentration Area / Mule Deer Severe Winter Range
- Aquatic Native Species Conservation Waters
- 100-year floodplain

Current site status:

- Excavation has been backfilled.
- Metal fencing surrounds former wellhead/spill location.
- Ruts and small piles of soil observed near the former wellhead.

See attached corrective actions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment: Ruts and small piles or soil observed near the former wellhead.

Corrective Action: Comply with Rule 1002.f.(2)C

Date: 02/12/2025

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type

OTHER

Comment: Metal fencing surrounds former wellhead/spill location. Excavation has been backfilled.

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	488931	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Remediation Project No. 37053 was created for the plugging and abandonment of the Windell 4-18A Wellhead wellhead and the removal of the associated flowline. The excavation at the location of the former wellhead has been backfilled. Metal fencing surrounds the former wellhead. No environmental impacts were visible. Quarterly reporting is required under Remediation Project No. 37053.

Corrective Action: _____

Date: _____

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404071837	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892658
717100047	ECMC Photo Log - Windell 4-18A Wellhead	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892653