

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/15/2025

Submitted Date:

01/28/2025

Document Number:

717100050

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
Rollins, Grace _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
Brown, Kari		kari.oakman@state.co.us	
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488845	SPILL OR RELEASE	CL	12/11/2024		-	Miller Fed 6-7A Flowline	EI

General Comment:

ECMC Environmental Field Inspection Report Summary
Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID 488845
Spill Name: Miller Fed 6-7A Flowline
Remediation Project #: 35462
Wellhead API #: 05-123-20706
Reported Date of Discovery: 12/09/2024
Date of Inspection: 01/15/2025

Spill is located within or adjacent to:
-Bald Eagle Roost Site
-Wetlands
-100-year floodplain
-Livestock rangeland

Current site status:
-Excavation has been backfilled.

See attached corrective actions. A Supplemental Form 27.

Inspected Facilities

Facility ID: 488845 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Remediation Project No. 35462 was created for the plugging and abandonment of the Miller Fed 6-7A wellhead and the removal of the associated flowline. The excavation associated with this spill has been backfilled. No environmental impacts were visible. Quarterly reporting was required under Remediation Project No. 35462; the last Form 27 for this project was submitted 9/25/2024 (Document No. 403927334).

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation Project No. 35462.

Date: 02/13/2025

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404071622	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892535
717100055	ECMC Photo Log - Miller Fed 6-7A Flowline	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892526