

Inspection/Audit Photos
Location: QB Energy 596-33C Pad
Location ID: 335880
Date: 01/30/2025



Photo # 3809 Entrance to location



Photo # 3849 Location

Inspection/Audit Photos
Location: QB Energy 596-33C Pad
Location ID: 335880
Date: 01/30/2025



Photo # 3810 Location



Photo # 3818 Location

Inspection/Audit Photos
Location: QB Energy 596-33C Pad
Location ID: 335880
Date: 01/30/2025



Photo # 3819 Location



Photo # 3846 Location

Inspection/Audit Photos
Location: QB Energy 596-33C Pad
Location ID: 335880
Date: 01/30/2025



Photo # 3848 Location



Photo # 3890 SW corner of location

Inspection/Audit Photos
Location: QB Energy 596-33C Pad
Location ID: 335880
Date: 01/30/2025



Photo # 3891 SE corner of location



Photo # 3892 NE corner of location

Inspection/Audit Photos
Location: QB Energy 596-33C Pad
Location ID: 335880
Date: 01/30/2025



Photo # 3893 NW corner of location



Photo # 3825 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos
Location: QB Energy 596-33C Pad
Location ID: 335880
Date: 01/30/2025



Photo # 3828 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 3829 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos
Location: QB Energy 596-33C Pad
Location ID: 335880
Date: 01/30/2025



Photo # 3832 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 3834 Wildlife hazard

Inspection/Audit Photos
Location: QB Energy 596-33C Pad
Location ID: 335880
Date: 01/30/2025



Photo # 3835 Wildlife hazard



Photo # 3839 Wildlife hazard

Inspection/Audit Photos
Location: QB Energy 596-33C Pad
Location ID: 335880
Date: 01/30/2025



Photo # 3842 Wildlife hazard



Photo # 3865 Open ended load line

Inspection/Audit Photos
Location: QB Energy 596-33C Pad
Location ID: 335880
Date: 01/30/2025



Photo # 3866 Open ended load line



Photo # 3869 Open ended load line

Inspection/Audit Photos
Location: QB Energy 596-33C Pad
Location ID: 335880
Date: 01/30/2025



Photo # 3870 Open ended load line




Photo # 3871 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos
Location: QB Energy 596-33C Pad
Location ID: 335880
Date: 01/30/2025



Photo # 3872 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 3876 Staining in secondary containment

Inspection/Audit Photos
Location: QB Energy 596-33C Pad
Location ID: 335880
Date: 01/30/2025



Photo # 3877 Staining in secondary containment



Photo # 3878 Staining in secondary containment

Inspection/Audit Photos
Location: QB Energy 596-33C Pad
Location ID: 335880
Date: 01/30/2025



Photo # 3882 Staining in secondary containment



Photo # 3880 Unused hoses